



- 1) Image of ambient air sampling location at Garage Rooftop of BOE building (Subject Building) located at 450 N Street, Sacramento.



- 2) Image of air sampling equipment located within interior of LCD-C-1 containment area at time of assessment. Note sheetrock repair at area formerly removed for inspection.



3) Image of reconstructed wall within interior of containment LCD-C-2 at time of assessment.



4) Image of interior entry chamber construction and air sampling activity performed within LCD-C-2 at time of assessment.



- 5) Image of baseboard removal, wall repair, and air sampling activity performed within LCD-C-3 at time of assessment.



- 6) Image of baseboard removal, wall repair, and air sampling activity performed within LCD-C-4 at time of assessment.



- 7) Image of air sampling equipment and HEPA filtered negative air machine as viewed from interior side of containment LCD-C-4 at time of assessment.



- 8) Image from hallway of LCD-C-5 containment area erected at restroom entry area.



- 9) Image of air sampling equipment and critical barriers erected within LCD-C-5 containment system at time of assessment.




- 10) Image of baseboard removal and wallboard repair following LCD's inspection within LCD-C-6 at time of clearance assessment.



11) Image of wallboard repaired following LCD inspection within LCD-C-7 containment at time of assessment.



12) Image of air sampling and air handling equipment within men's restroom LCD-C-8 containment at time of assessment.



13) Image of wallboard repaired following LCD inspection within LCD-C-9 containment at time of assessment.



14) Image of ambient air sampling location on 23rd Floor Western Balcony of BOE building performed at conclusion of interior clearance inspection sampling.